1	14	4	12	0	1 /	-
+/	Ι.	Т	12	U.	LΙ	0

GAS TRANSMISSION WORK ORDER

SEU .

WORKORDER

WORK ORDER #: 6115589

PMNUM:

PARENT WO #:

DESCRIPTION: VALVE TESTING FREW-2 (SEE COMMENTS BELOW) 037-00665

TARGET START DATE:

TARGET COMP DATE: 5/5/2016

SCHEDULE START: SCHEDULE FINISH:

ROUTE NUMBER:

STATUS: INPRG

REQUESTED BY: DMAINE REPORT DATE: 4/11/2016

UN

PM ACTIVITY CLASS:

ASSET #: 24848

ASSET DESCRIPTION: GROUP 4 WELLS

LOCATION ID: AC-GROUP 4 WELLS

LOC, DESCRIPTION: FREW 2, 4, 5, 7, 8

PHYSICAL LOCATION:

RESPONSIBLE SUPERVISOR / OWNER

WORK TYPE

PRIORITY

ACCOUNT INFO

FIELD MAINT /

CM

2

26357.003

REMARKS: PERFORMED FUNCTION TEST 4-8-16

VALUES LISTED BELOW.

Date Completed

Completed By

SAFETY CHECKLIST COMPLETED?

Estimated Labor Hours

Labor Code/Craft

Quantity

Planned Hours

Actual Hours . 25

JT MACK

0

COMMENTS:

PERFORM FUNCTION TEST ON THE MASTER VALVE, TUBING PRODUCTION WING VALVE, CASING PRODUCTION WING VALVE, TUBING KILL WING VALVE & CASING KILL WING VALVE.

LOCATION METERS:

LOG: